

Swan Roof Consulting Inc. Suite 107, 5-8720 Macleod Trail SE Calgary, AB, T2H OM4

T: 403.288.5044 F: 403.288.5021

E: info@swanrc.ca

Steep-Slope Roofing Quality Assurance Inspection Report

Report No. 12	Report Type:	Pre-Start □	Initial	Interim ⊠	Final	Post Final		Report Date: July 5, 2012
Inspector File N	o: 12-483					I	New 🗌	Reroof ⊠
					Area in	Squares:		300
Project Name:	С	haparral E	Estates					
Address:	С	Chaparral Ridge Terrace SE						
City:	С	algary, AE	3					
Roofing Contract	ctor: R	oyal Roof	ing					
	·							

DESCRIPTION OF OBSERVED ROOFING OPERATIONS								
Date of Site Visit:	July 5, 2012	Time:	AM					
Roof/Building Section:	59/61/63/65/67							
Current Application Location:	59/61/63/65/67							
Weather Conditions:	Sunny	Temp.:	17 °C					
Onsite Journeyman/Foreman	Burhan	Crew Size:	6					

Roof Observations:

- 1. Roofing contractor on site at time of observation.
- 2. Previous Day's Application: **30SQ Upper Level.**
 - a. New roofing system appears to have been installed with the exception of the ridge vents/caps, hip caps and metal wall flashings.
 - i) Galvanized step flashings over the four chimneys have been re-used- no new pre-painted step flash has been applied as per specification.
 - ii) No eave protector has been applied at 12" onto the wall junction of chimney as per specification.
 - b. The pre painted 28 gauge metal drip edge has been applied along the eaves and rakes.
 - c. The 28 gauge pre painted metal W valleys have been installed. The synthetic underlayment felt has been applied under the valleys.
 - d. The Malarky Legacy SBS shingles have been applied mechanically fastened.
 - e. Six new neoprene gaskets and six new exhaust vents have been installed.
- 3. Today's application: 20SQ—Lower Level.
 - a. Roofing contractor has applied the pre painted 28 gauge metal drip edge along the eaves.
 - b. 36" of Lastobond 195 self-adhered eave protector along the eave. The eave protector has been run parallel with the eave.
 - c. The Titanium UDL Synthetic underlayment felt all over roof field and under valleys- has been run parallel with eave.
 - d. The starter strips along the eaves and rakes have been applied.
 - e. Roofing contractor is in the process of installing the Malarky Legacy SBS shingles- mechanically attached.
 - f. Four standard air vents and two exhaust vents have been installed.
- 4. Project Progress as of today:

a. Building 74/76/78/80 & Building 64/66/68/70

i) New roofing system have been completed with the exception of the ridge vents/caps, hip caps, new step flash and new wall flash as per specification.

Project Name: Chaparral Estates Report No.: 12 Page 2 of 2

Report Distribution:

andrew.prairie@telus.net;
chenko@shaw.ca; Owner:

ilia.pengu@gmail.com Roofing Contractor:

Attending Inspector Name: Signature:	Albert Gashi	Mor agli	
Report Reviewed by: Signature:	Bill Elliott, RRO	B.). Elleth	