

Swan Roof Consulting Inc. Suite 107, 5-8720 Macleod Trail SE Calgary, AB, T2H OM4

T: 403.288.5044 F: 403.288.5021

E: info@swanrc.ca

Steep-Slope Roofing Quality Assurance Inspection Report

Inspector File No: 1	12-483							
						Nev	w \square	Reroof 🛚
					A : :-	Carrage		070
					Area in	Squares:		676
Project Name:	C	haparral E	states					
Address:	С	haparral R	idge Te	errace SE				
City:	С	algary, AB						
Roofing Contractor:	R	oyal Roofii	ng					

DESCRIPTION OF OBSERVED ROOFING OPERATIONS							
Date of Site Visit:	July 19, 2012	Time: A	λ.M				
Roof/Building Section:	31-39						
Current Application Location:	31-39						
Weather Conditions:	Sunny	Temp.:	19 °C				
Onsite Journeyman/Foreman	Burhan	Crew Size:	6				

Roof Observations:

- 1. Roofing contractor on site at time of the observations.
- 2. Previous Day's Applications: 25 SQ Lower Level/Window Bays
 - a. New roofing system appears to have been applied with the exceptions of the ridge vents/caps, hip caps and the metal wall flashings.
 - b. The Legacy SBS Malarkey shingles have been fastened.
 - c. Five standard air vents and three exhaust vents have been installed.
 - d. New step flashing is required to be installed at the wall junctions over the garage sections.
 - e. The eave protector has been applied all over the window bay areas.
- 3. Today's Applications: 15 SQ Lower Level/Upper Level
 - a. Roofing contractor has applied the 28 gauge pre painted drip edge along the eaves and along the rakes.
 - b. Roofing contractor has applied the eave protector along the eaves at 36" onto the field the eave protector has been run parallel with the eaves.
 - c. Roofing contractor has applied the synthetic underlayment felt Titanium UDL over the roofs field. The underlayment felt has been run parallel with the eaves.
 - d. Roofing contractor has applied the BP starter strips along the eaves.
 - e. Roofing contractor is in the process of applying the Legacy SBS Malarkey shingles fastened.
 - f. Upper level: Roofing contractor is in the process of installing the Alaskan SBS Malarkey hip caps.
- 4. The president of the board of the association Joana has requested that the association would like to see one building completed include the metal wall flashings.
 - a. The color of the wall flashings over the window is open per selection most likely to match the fascia white or the sidings tan.

Project Name: Chaparral Estates Report No.: 22 Page 2 of 2

Report Distribution:

Email: andrew.prairie@telus.net Owner: Email: ilia.pengu@gmail.com Roofing Contractor:

Attending Inspector Name: Signature:	Albert Gashi	Mor Caffi	□ Apprentice or □ ARCA accepted
Report Reviewed by: Signature:	Bill Elliott, RRO	B.). Ellett	