



Swan Roof Consulting Inc.  
Suite 107, 5-8720 Macleod Trail SE  
Calgary, AB, T2H 0M4  
T: 403.288.5044 F: 403.288.5021  
E: info@swanrc.ca

## Steep-Slope Roofing Quality Assurance Inspection Report

**Report No.** 19      **Report Type:**    Pre-Start     Initial     Interim     Final     Post Final       **Report Date:** July 14 2012  
**Inspector File No:** 12-483      New     Reroof

		Area in Squares:	676 SQ
<b>Project Name:</b>	Chaparral Estates		
<b>Address:</b>	Chaparral Ridge Terrace SE		
<b>City:</b>	Calgary, AB		
<b>Roofing Contractor:</b>	Royal Roofing		

### DESCRIPTION OF OBSERVED ROOFING OPERATIONS

<b>Date of Site Visit:</b>	July 14, 2012	<b>Time:</b>	10:50 A.M
<b>Roof/Building Section:</b>	41-51		
<b>Current Application Location:</b>	41-51		
<b>Weather Conditions:</b>	Sunny	<b>Temp.:</b>	19 °C
<b>Onsite Journeyman/Foreman</b>	Burhan	<b>Crew Size:</b>	5

#### Roof Observations:

1. Roofing contractor on site at time of the observations.
2. Previous Day's Applications: **Upper Level**
  - a. New roofing system appears to have been applied with the exceptions of the ridge vents, ridge caps and the metal wall flashings.
  - b. The Legacy SBS Malarkey shingles have been mechanically fastened.
  - c. The self-adhered eave protector has been applied at 36" onto the roofs field and all over the window bay areas.
  - d. The synthetic Titanium UDL roof underlayment has been applied all over the roofs field and under the valleys.
  - e. Six standard air vents have been installed above the garage areas.
3. Today's Applications: **Lower Levels**
  - a. Roofing contractor is in the process of installing the Alaskan SBS Malarkey caps over the hips over the garage areas.
  - b. Roofing contractor is in the process of applying the Legacy SBS Malarkey shingles over the garage areas and the window bays above the garage areas.
  - c. Ground area free of sharp materials at time of the observations.
  - d. Ridge vents to be installed in the remaining areas of the upper level of the roof.

#### Concerns/Issues:

1. Contamination spill on the drive way area in front of the unit 64 to be cleaned.

**Report Distribution:**

Owner: Email: [andrew.prairie@telus.net](mailto:andrew.prairie@telus.net)  
Roofing Contractor: Email: [ilia.pengu@gmail.com](mailto:ilia.pengu@gmail.com)

Attending Inspector Name: Signature:	Albert Gashi		<input checked="" type="checkbox"/> Apprentice or <input type="checkbox"/> ARCA accepted
Report Reviewed by: Signature:	Bill Elliott, RRO		