



Swan Roof Consulting Inc.  
Suite 107, 5-8720 Macleod Trail SE  
Calgary, AB, T2H 0M4  
T: 403.288.5044 F: 403.288.5021  
E: info@swanrc.ca

## Steep-Slope Roofing Quality Assurance Inspection Report

Report No. 10      Report Type:    Pre-Start     Initial     Interim     Final     Post Final       Report Date: July 3, 2012  
Inspector File No: 12-483      New     Reroof

		Area in Squares:	300
Project Name:	Chaparral Estates		
Address:	Chaparral Ridge Terrace SE		
City:	Calgary, AB		
Roofing Contractor:	Royal Roofing		

### DESCRIPTION OF OBSERVED ROOFING OPERATIONS

Date of Site Visit:	July 3, 2012	Time:	AM
Roof/Building Section:	59/61/6365/67		
Current Application Location:	59/61/63/65/67		
Weather Conditions:	Sunny/ Cloudy	Temp.:	13 °C
Onsite Journeyman/Foreman	Burhan	Crew Size:	5

#### Roof Observations:

1. Roofing contractor on site at time of observation.
2. Today's Application: **10SQ**
  - a. Roofing contractor has applied the pre-painted 28 gauge metal drip edge along the eaves and rakes.
  - b. Roofing contractor has applied 36" of Lastobond 195 self-adhered eave protector along the eaves. The eaves protector has been run parallel with the eaves.
  - c. Roofing contractor has applied the Titanium UDL Synthetic underlayment felt over the roofs field and under valleys. The underlayment felt has been run parallel with the eaves.
  - d. Roofing contractor has installed the 28 gauge metal pre-painted W valleys under the valleys.
  - e. Roofing contractor expects to install the starter strips and the Malarky SBS over the roof field by days end.
3. The ground area where daily activity occurs is in order. Roofing materials have been placed in designated areas.

#### Concerns/Issues:

1. Occupational Health and Safety is on site today.
  - a. Roofing contractor has been cautioned twice about safety violations but is allowed to continue work for the day.

**Report Distribution:**

Owner: [andrew.prairie@telus.net](mailto:andrew.prairie@telus.net);  
[tchenko@shaw.ca](mailto:tchenko@shaw.ca) ;  
Roofing Contractor: [ilia.pengu@gmail.com](mailto:ilia.pengu@gmail.com)

Attending Inspector Name: Signature:	Albert Gashi		<input checked="" type="checkbox"/> Apprentice or <input type="checkbox"/> ARCA accepted
Report Reviewed by: Signature:	Bill Elliott, RRO		