

Donart No

Swan Roof Consulting Inc. Suite 107, 5-8720 Macleod Trail SE Calgary, AB, T2H OM4

T: 403.288.5044 F: 403.288.5021

Papart Data:

Temp.:

Crew Size:

E: info@swanrc.ca

11 °C

0

Steep-Slope Roofing Quality Assurance Inspection Report

Einal

32				August 02, 2012
Inspector File No: 12-483 New ☐ Reroof ☒				
		Are	a in Squares:	676 SQ
Project Name:	Chaparral Estat	tes		
Address:	Chaparral Ridge	e Terrace SE		
City:	Calgary, AB			
Roofing Contractor:	Royal Roofing			
	RIPTION OF OBSE	RVED ROOFING	OPERATIONS	,
Date of Site Visit:	August (02, 2012	Time	e: 08:30 A.M
Roof/Building Section:	5-15		·	
Current Application Locat	ion: 5-15	·		·

Initial

Roof Observations:

Weather Conditions:

Onsite Journeyman/Foreman

1. No Roofing Contractor on site at the time of the observation.

Papart Type:

Dra Start

- 2. Previous Day's Applications: Building 5-15 Upper Level/South
 - a. Roofing system appear to have been applied with the exception of the ridge vents and caps, hip caps and the wall flashings.

Cloudy Rainy

N/A

- b. Five neoprene gaskets and five exhaust vents have been installed.
- c. The 28 gauge pre-painted W valleys have been installed. The synthetic underlayment felt has been applied under the valleys.
- 3. Previous Day's Applications: Building 5-15 Upper Level/North
 - a. The Roofing Contractor has applied the drip edge along the eaves and rakes.
 - b. The Roofing Contractor has applied the eave protector at 36" along the eaves.
 - c. The Roofing Contractor has applied the Titanium UDL synthetic underlayment felt all over the field.
- 4. The Roofing Contractor was expected to apply the Legacy SBS Malarkey shingles on the north side of the roof before leaving the site.

Concerns/Issues:

- 1. Roofing materials on the back and the front of building 19 to 29 are expected to be removed and placed at the designated materials parking areas.
- 2. The Synthetic felt over the ridges and the hips is required to be overlaid at 6" and above.
- 3. Several sections of the hips and ridges the deck is exposed.

Project Name: Chaparral Estates Report No.: 32 Page 2 of 2

Report Distribution:

Email: andrew.prairie@telus.net Owner: Email: ilia.pengu@gmail.com Roofing Contractor:

Attending Inspector Name: Signature:	Albert Gashi	Mer Coffii	
Report Reviewed by: Signature:	Bill Elliott, RRO	13-). Elleth	